

TECHNIQUE

Soldering Techniques for Lead Attachment to Strain Gages with Solder Dots

Table of Contents

[Introduction](#)

[Soldering Temperature](#)

[Soldering Tip Design](#)

[Fluxing](#)

[Bead Formation](#)

[Hold-Down](#)

[Soldering Compatibilities](#)

Total of 7 Pages



<http://www.measurementsgroup.com>

A Measurements Group **Strain★Smart** Hypertext Publication

Also available in printed form as Measurements Group Tech Tip TT-606

TECHNIQUE

Soldering Techniques for Lead Attachment to Strain Gages with Solder Dots

Introduction

Many gages are now purchased with integral solder dots. These offer advantages of accurately controlled solder joint size, convenience when working in confined areas, and of having pretinned "hard-to-solder" alloys such as [Iso-elastic](#) and [Karma](#). Controlled joint size, in turn, helps to increase gage fatigue life, and minimizes thermocouple effects.

If proper installation techniques are used, there should be no difficulty experienced in obtaining well-soldered connections; but care must be exercised. Open-faced gages with [Option S](#) (solder dots only) should be coated with adhesive at the time of installation. Such encapsulation effectively prevents dot enlargement and undesirable spreading during subsequent soldering steps. To expose the dots, lightly abrade with 400-grit [silicon-carbide paper](#) or simply solder through this overcoat. Encapsulated gages do not require additional coating with adhesive.

The following pages are important guidelines.



Soldering Techniques for Lead Attachment to Strain Gages with Solder Dots

Solder Temperature


"T" backed gages with [Option S](#), and "S" Series gages, have dots composed of +570 deg F (+300 deg C) lead-tin-silver solder. Micro-Measurements wire solders have melting points ranging from +361 to +570 deg F (+183 to +300 deg C); the most common are the +361 and +570 deg F (+183 and +300 deg C) solder wire with rosin-core flux. Solid wires are also available, including a popular +430 deg F (+220 deg C) type.

A temperature-controlled soldering station, such as the [Micro-Measurements Mark V](#) or [Mark VII](#) Soldering Unit, is recommended. Tip temperature should be high enough to assure good wetting of the solder but not so high as to remove the dots, vaporize flux, or hinder keeping the iron properly tinned and clean. Unfortunately, most uncontrolled irons are quite capable of tip temperatures in excess of +900 deg F (+480 deg C), which is much too high for general strain gage soldering.




Soldering Techniques for Lead Attachment to Strain Gages with Solder Dots

Solder Tip Design



Never solder with a sharply pointed tip (shown above). A hot point applied to a solder dot usually draws out the solder. Use a clean, flat 1/16-in (1.5-mm) wide chisel or screwdriver type tip held flat against the work, as shown below.



Soldering Techniques for Lead Attachment to Strain Gages with Solder Dots

Fluxing

Proper fluxing is essential. Enough flux, either from melting of flux-core solder or adding [M-Flux AR](#) separately, must be introduced to assure complete wetting action. This is particularly important with +570 deg F (+300 deg C) solder as there is an increased tendency for the flux to be boiled away at higher temperatures.


If "spikes" are produced instead of smooth beads, it is a sign of inadequate fluxing, dwelling too long with the iron, and/or an improper iron temperature.

Rosin flux should always be used in making connections to [Option S](#) gages. All flux residue should be thoroughly removed with [Rosin Solvent](#).




Soldering Techniques for Lead Attachment to Strain Gages with Solder Dots

Bead Formation




It is important to first build up a well-formed bead on each dot as shown above. This is done by laying rosin-core solder wire across each dot, firmly applying the iron for one second, then simultaneously lifting both wire and iron (shown below). If the first attempt fails, simply repeat this procedure, making certain to use enough [flux](#). Feeding a cored [solder](#) into the joint area during heat application will increase the available flux.



Soldering Techniques for Lead Attachment to Strain Gages with Solder Dots

Hold-Down


Each connecting wire must be carefully and firmly anchored in place with spring loading against the dot bead, as illustrated below, before soldering the connection. When this is properly done, a one-second touch of a hot iron and fresh [solder](#) with [flux](#) should complete the process.



Soldering Techniques for Lead Attachment to Strain Gages with Solder Dots

Solder Compatibilities

All Micro-Measurements [solders](#) are compatible with each other. Of course, if one type is incorporated in the dot and another added from wire, a mixture is produced. This new alloy cannot be expected to have melting and strength properties any better than those of the lower temperature component. In special cases of mixing +430 deg and +570 deg F (+220 deg and +300 deg C) solders, a final alloy similar to +361 deg F (+183 deg C) solder can be encountered.



The figure above illustrates a typical installation. Note that solder dot ([Option S](#) or [SE](#)) gages are always connected to bonded terminals for strength. Refer to Tech Tip TT-603, [The Proper Use of Bondable Terminals in Strain Gage Applications](#), for other arrangements.

Refer to [Catalog A-110](#) for a description of Micro-Measurements [soldering supplies and accessories](#), and to Tech Tip TT-609, [Strain Gage Soldering Techniques](#), for a detailed discussion on general strain gage soldering techniques.



